
Original doors from upstairs being prepared for rear entrance closet



Burying the security wiring



"J.C." looking for squirrels



Exterior panels for entrance



1860 flooring for a bedroom




Checking on progress



I guess they're doing a good job



We need a railing for these stairs



Makes me dizzy



Insulated lower door panel



Above the pencil is an original signature from 1843



Couldn't quite make it out



New and old - entrance being assembled



Original casings ready for stripping and sanding (lead paint)




Tools of the trade – more casings await revival



A door awaits installation



Restored casing has been primed and painted, ready to install



Ready for primer and finish paint



Assembly area



Bits and pieces ready for sidelight installation after prep work



A soft spot



End grain on an old Fir board



Strip the old putty and remove the glass before prepping the sidelight




A wintry day at The Farm



Removing the putty and glass from the 1843 transom window



Dave gives up his jacket for today



Prepping door openings for casings



Casing edges must be stripped of old wallpaper and plaster and painted before installation



This door will lead to the basement



Rear entrance closet doors (1843)



A bathroom vanity arrives – Walnut facings made from trees cut down on the property



Period float glass to replace some of the front entrance panes






Dave provides an option for painting the entrance door (1860)



1860 casing in the Great Room



1860 entrance door – painted and ready for approval



A red tail Hawk looks for lunch

