
### Fruits of thy labour – the floors!



### Sanded and sanded they were




### A lot of sanding where the old floors had been painted



### A lot of sanding to level the bumps



### A lot of care at transition points




### Less sanding of the old original flooring which had never been finished




## Leave the defects, they add charachter



#### Four coats of Varathane




### In the pantry under the stairs




#### A warm glow in the living room



## Cast iron cold air register goes in the hole



#### Steve's office



### Sunlight on the floor of the dining room



### Steve did the sanding




### And Kay did the finishing



#### You folks do beautiful work



### Vanity top in the girls bathroom



## The boys finished the ceiling in Kay's office



# Flooring installer putting down the underlay



#### **Towards the basement stairs**



# Cardboard template so there's no mistakes



### Two piece bathroom floor underlay




### The air stapler broke so he had to leave



### Master bedroom reclaimed flooring



### Donated by a kind neighbour



#### **Awaits the sander**



### Cast iron tub receives bottom paint



### **Bayfield River is back to normal**



### A historic stone house was burned in a fire while I was away



### Used only for storage it's believed critters started the fire – big loss



### I found this horse while we were on holidays



### And a design to consider for another project in 2009

